

St Athan Northern Access Road, FCA

Flood Consequence Assessment Appendix C- Site Walkover Photographs

Welsh Government

Project Number: 60509148

3 March 2017

Quality information

Prepared by		Checked by		Approved	Approved by	
Laura Gibbons						
Revision His	story					
Revision	Revision date	Details	Authorized	Name	Position	
Distribution	List					
# Hard Copies PDF Required		Association /	Company Name			

Р	rer	าล	red	fο	r.
	-	<i>,</i> α	u	10	

Welsh Government

Prepared by:

Laura Gibbons

AECOM Infrastructure & Environment UK Limited The Crescent Centre Temple Back Bristol BS1 6EZ UK

T: +44 (117) 917 1200 aecom.com

© 2016 AECOM Infrastructure & Environment UK Limited. All Rights Reserved.


This document has been prepared by AECOM Infrastructure & Environment UK Limited ("AECOM") for sole use of our client (the "Client") in accordance with generally accepted consultancy principles, the budget for fees and the terms of reference agreed between AECOM and the Client. Any information provided by third parties and referred to herein has not been checked or verified by AECOM, unless otherwise expressly stated in the document. No third party may rely upon this document without the prior and express written agreement of AECOM.

Figures

gure 1-Approximate Photograph Location Map5
gure 2- Froglands Farm Bridge6
gure 3- Looking Downstream from Froglands Farm Bridge7
gure 4-Looking Upstream from Froglands Farm Bridge7
gure 5- Froglands Farm, with Boverton Brook to Left of Photo8
gure 6- Boverton Brook Upstream of Froglands Farm8
gure 7-Outlet of Culvert on Boverton Brook9
gure 8-Boverton Brook, Upstream Extent of Received NRW Model9
gure 9- Boverton Brook, Looking Upstream from Downstream Extent of Model Extension
gure 10- Looking Downstream at Downstream Extent of Boverton Brook Extension10
gure 11- Typical Overgrown Section of Boverton Brook11
gure 12- Upstream Extent of Boverton Brook Model Extension
gure 6- Boverton Brook Upstream of Froglands Farm

1. 2nd November Site Walkover Photographs

A site walkover was conducted on 2nd November 2016. Photographs from this site visit are contained below. The approximate location of these photographs is shown in Figure 1. The proposed NAR is shown in green, the received model in blue, and the model extension in Pink.



Prepared for: Welsh Government



Figure 2- Froglands Farm Bridge



Figure 3- Looking Downstream from Froglands Farm Bridge



Figure 4-Looking Upstream from Froglands Farm Bridge



Figure 5- Froglands Farm, with Boverton Brook to Left of Photo



Figure 6- Boverton Brook Upstream of Froglands Farm



Figure 7-Outlet of Culvert on Boverton Brook



Figure 8-Boverton Brook, Upstream Extent of Received NRW Model



Figure 9- Boverton Brook, Looking Upstream from Downstream Extent of Model Extension



Figure 10- Looking Downstream at Downstream Extent of Boverton Brook Extension



Figure 11- Typical Overgrown Section of Boverton Brook



Figure 12- Upstream Extent of Boverton Brook Model Extension