

Appendix H Photographic Records

St. Athan Northern Access Road

Photo No.
1**Description:**SK501 Excavation
(23/11/2016)**Photo No.**
2**Description:**SK502 Excavation
(23/11/2016)

Photo No.
3**Description:**SK503 Excavation
(25/11/2016)**Photo No.**
4**Description:**SK504 Excavation
(25/11/2016)

St. Athan Northern Access Road

Photo No.
5**Description:**SK505 Excavation
(24/11/2016)**Photo No.**
6**Description:**SK506 Excavation
(24/11/2016)

St. Athan Northern Access Road

Photo No.
7**Description:**SK507 Excavation
(23/11/2016)**Photo No.**
8**Description:**SK508 Excavation
(22/11/2016)

Photo No.
9**Description:**SK509 Excavation
(22/11/16)**Photo No.**
10**Description:**SK510 Excavation
(22/11/2016)

Photo No.
11**Description:**TP501 Excavation
(22/11/16)**Photo No.**
12**Description:**BH501 Buried service
inspection pit (30/11/2016)

St. Athan Northern Access Road

Photo No.
13

Description:

BH501 Rock core: 1.00m – 4.00m bgl (30/11/2016)



Photo No.
14

Description:

BH501 Rock core: 4.00m – 7.00m bgl (30/11/2016)



St. Athan Northern Access Road

Photo No.
15

Description:

BH501 Rock core: 7.00m – 8.50m bgl (30/11/2016)



Photo No.
16

Description:

BH501 Complete with install (30/11/2016)



Photo No.
17

Description:

BH502 Buried service inspection pit: (21/11/2016)



Photo No.
18

Description:

BH502 Rock core: 2.50m – 5.50m bgl (01/12/2016)



St. Athan Northern Access Road

Photo No.
19

Description:

BH502 Rock core: 5.50m – 8.00m bgl (01/12/2016)



Photo No.
20

Description:

BH502 Complete with install (01/12/2016)



St. Athan Northern Access Road

Photo No.
21**Description:**BH503 Buried service
inspection pit: (21/11/2016)**Photo No.**
22**Description:**BH503 Rock core: 1.00m –
4.00m bgl (29/11/16)

Photo No.
23

Description:

BH503 Rock core: 4.00m – 7.00m bgl (29/11/2016)



Photo No.
24

Description:

BH503 Rock core: 7.00m – 8.50m bgl (29/11/2016)



St. Athan Northern Access Road

Photo No.
25**Description:**BH503 Complete with install
(29/11/2016)**Photo No.**
26**Description:**BH504 Buried service
inspection pit: (21/11/2016)

Photo No.
27

Description:

BH504 Rock core: 1.00m – 4.00m bgl (28/11/2016)



Photo No.
28

Description:

BH504 Rock core: 4.00m – 6.80m bgl (28/11/2016)



Photo No.
29

Description:

BH504 Rock core: 6.80m – 8.30m bgl (28/11/2016)



Photo No.
30

Description:

BH504 Complete with install (28/11/2016)



